

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:

Company Mark Reynolds Resident Agent

Inspection Report

Permit Number:	C0150025
Inspection Type:	PARTIAL
Inspection Date:	Monday, February 09, 2004
Start Date/Time:	02/09/2004 1:15:00 PM
End Date/Time:	02/09/2004 2:45:00 PM
Last Inspection:	Wednesday, January 14, 2004

Inspector: <u>Pete Hess, Environmental Scientist III</u>
Weather: <u>Clear, cold; temp range 20's to 30's F</u>

InspectionID Report Number: 170

Accepted by: pgrubaug 02/13/2004

Permitee: CO-OP MINING CO
Operator: CO-OP MINING CO

Site: BEAR CANYON MINE

Address: PO BOX 1245, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages			Mineral Ownership	Types of Operations
	3,336.18	Total Permitted	✓ Federal	✓ Underground
	36.64	Total Disturbed	☐ State	Surface
		Phase I	☐ County	Loadout
		Phase II	✓ Fee	Processing
I		Phase III	Other	Penrocessing

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The permitte continues to develop the rock tunnels associated with the #4 Mine, Wild Horse Ridge addition, Tank seam. To date, each tunnel has been developed approximately 350 feet into the mountain, not including a cross cut connection. The permittee has proposed that some of the muck being generated from the tunnel development be used as backfill material. The material has been tested for acid and toxic forming potential and the results of the analyses have been forwarded to the Salt Lake technical staff.

Inspector's Signature:	Date	Tuesday, February 10, 2004

Pete Hess, Environmental Scientist III Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Monday, February 09, 2004 Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓			
6.	Disposal of Excess Spoil, Fills, Benches	✓		✓	
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓			
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation	✓		✓	
12.	Backfilling And Grading		✓		
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing	✓		✓	
16.	b Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check				
20.	Air Quality Permit	✓			
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Monday, February 09, 2004

Page 3 of 4

4.a Hydrologic Balance: Diversions

The site received a new snow accumulation on February 7th and 8th. Many diversions remain under snow, and as such, cannot be inspected. The snow removal and storage process was discussed with Mr. Reynolds.

4.d Hydrologic Balance: Water Monitoring

The permittee's water monitoring information for the third quarter of 2003 is missing a carbonate value for monitoring site SBC-17 for August 5. A review of the laboratory analysis sheet during today's inspection revealed that the lab did not report a carbonate value; a telephone call to CT&E in Huntington, Utah on 2/10/2004 revealed that the permittee failed to request this parameter (carbonate) when the sample was submitted. However, the lab reported that the value for this parameter for the 8/5 sample was less than 5 mg/l. This was reported to the Salt Lake hydrologist who will have the value entered into the Division EDI for the permittee. As noted during today's field inspection, the Bear Creek drainage was frozen and snow covered.

6. Disposal of Excess Spoil, Fills, Benches

As noted in the summary, the permittee is proposing to use muck from the #4 Mine rock tunnel development as backfill material. The permittee is storing that material at various locations until a Division approval is received.

8. Noncoal Waste

A small trailer located on the #4 Mine portal pad containing 5 gallon lubricant containers and cardboard boxes was observed to be overflowing. Mr. Reynolds agreed to have the trash picked up and removed to the lower Canyon until transport off the permit area could be arranged.

11. Contemporaneous Reclamation

There has been no new activity relative to the reclamation of the #2 Mine (Tank seam) access road. The backfilling of the #1 Mine seals has not seen any activity. The #1 Mine ventilation fan and the two belt portals associated with the Blind Canyon and Hiawatha seams will require a great deal of dismantling prior to backfilling of those areas. It is anticipated that there will be no activity in these areas until the permittee has developed the #4 Mine to the point that coal production is constant.

16.a Roads: Construction, Maintenance, Surfacing

All safety berms along the #3 and #4 Mine access roads are under snow. Some thawing was occuring this day, and the roads were muddy in some areas. To date, no road base has been placed due the limited production which the mine is currently experiencing.

Permit Number: C0150025 Inspection Type: PARTIAL

Inspection Date: Monday, February 09, 2004 Page 4 of 4

16.b Roads: Drainage Controls

All roads and ditches along the Mine's access roads were under frozen compacted snow.

18. Support Facilities, Utility Installations

The permittee has installed a ventilation fan adjacent to the #1 tunnel accessing the #4 Mine. The completion of the duct work to connect the fan to the #1 tunnel face-up is pending. The electrical work to power the fan also needs completion.